

SUPERIOR ROLL SHADE AWNINGS

XL 3000 SERIES MODEL

CUSTOM MANUFACTURED & DISTRIBUTED BY:
ROLL SCREEN SOLUTIONS, LLC. - SERVING ALL OF CENTRAL FLORIDA

CARE OF YOUR NEW SUPERIOR ROLL SHADE AWNING

CONGRATULATIONS ON YOUR DECISION TO PURCHASE A SUPERIOR ROLL SHADE AWNING SYSTEM. OUR AWNING SYSTEMS ARE RECOGNIZED FOR THEIR UNSURPASSED QUALITY, RUGGEDNESS AND BEAUTY. VIRTUALLY NO MAINTENANCE IS REQUIRED: HOWEVER, YOU MAY WISH TO WIPE THE FRAME PERIODICALLY USING A SOFT CLOTH WITH PLAIN WATER OR MILD SOAP.

FABRIC: SUPERIOR ROLL SHADE AWNINGS ARE MADE FROM 100% SOLUTION DYED ACRYLIC FABRIC. THEY ARE GUARANTEED FOR FIVE YEARS AGAINST EXCESSIVE LOSS OF COLOR OR STRENGTH FROM NORMAL EXPOSURE, INCLUDING SUNLIGHT, MILDEW, ROT, AND ATMOSPHERIC CHEMICALS. YOUR ACRYLIC AWNING FABRIC HAS BEEN TREATED TO PROVIDE WATER REPELLENCY, BUT BECAUSE THE FABRIC IS WOVEN, YOU MAY EXPERIENCE SOME WEEPING OR TINY PIN HOLES. IF THIS OCCURS, SPRAY THE AREA WITH SCOTCH GUARD TO SEAL FABRIC ONCE AGAIN. WE RECOMMEND THAT YOU OCCASIONALLY SPRAY THE FABRIC WITH ACRYLIC/WOOL CARPET CLEANER LIQUID OR FOAM TO ENSURE LONGER FABRIC LIFE. NO SCRUBBING OF FABRIC IS REQUIRED. JUST SPRAY ON CLEANER AND IT WILL EAT AWAY DIRT FOR 1-2 WEEKS.

CARE AND CLEANING: YOUR AWNING FABRIC SHOULD BE CLEANED REGULARLY BEFORE DIRT, BIRD DROPPINGS, ETC. ARE ALLOWED TO ACCUMULATE AND BECOME EMBEDDED INTO THE FABRIC. THE FABRIC CAN BE CLEANED WITHOUT REMOVING IT FROM THE FRAME BY BRUSHING OFF ANY LOOSE SOIL AND HOSING OFF WITH WATER. IF THERE ARE AREAS THAT DO NOT COME CLEAN WITH THIS METHOD, ADD MILD SOAP, SUCH AS NON-DETERGENT CAR WASH TO LUKE-WARM WATER AND LIGHTLY CLEAN THE FABRIC WITH A SPONGE OR SOFT CLOTH. RINSE THOROUGHLY TO REMOVE SOAP AND LET DRY BEFORE RETRACTING THE AWNING. DO NOT USE BLEACH OR DETERGENTS, AND NEVER DRY THE FABRIC USING HEAT OR STEAM PRESS. SCOTCH GUARD COATING SHOULD BE REAPPLIED AFTER 2-3 YEARS FOR LONGEVITY OF FABRIC. IT IS IMPORTANT NOT TO PRESSURE CLEAN OR HOSE MOTOR AND AWNING FRAME AS THIS WILL DAMAGE THE SYSTEM AND VOID THE WARRANTIES. A HOSE CAN PROVIDE MUCH MORE FORCE AND WATER VOLUME THAN RAIN AND PRESSURE CLEANING IS ABSOLUTELY DESTRUCTIVE.

FRAME: SUPERIOR ROLL SHADE AWNING FRAMES SHOULD OCCASIONALLY BE CLEANED OFF WITH A SPONGE AND WATER. USE CLEAR SILICONE SPRAY FOR ARM CABLES AND MOVING PARTS AFTER THE UNIT IS DRY. AVOID SPRAYING SILICONE ON THE FABRIC SINCE THIS MAY CAUSE DISCOLORATION. IN SEASHORE AREAS THE FRAME WORK SHOULD BE CLEANED EVERY 2-3 WEEKS.

MOTORS: MOTORS ARE SELF-CONTAINED AND REQUIRE LITTLE OR NO MAINTENANCE. IF THE MOTOR GOES OUT OF ADJUSTMENT OR FAILS TO FUNCTION PROPERLY, CONTACT SUPERIOR ROLL SHADE AWNINGS. WE WILL OPEN ANY FAILED MOTORS AT THE CUSTOMERS' LOCATION TO RULE OUT THE POSSIBILITY OF PRESSURE CLEANING OR DIRECT HOSING DAMAGE OR STORM RAIN DAMAGE. IF WATER HAS BEEN FORCED INTO MOTOR OR FRAME, THAN WATER OR RUST WILL BE REVEALED AND SHOWN TO CUSTOMER ON THE SPOT. WARRANTEE WILL BE VOID DO TO THIS SITUATION SO, PLEASE DO NOT LET ANYONE HOSE OR PRESSURE CLEAN YOUR AWNING FRAME OR MOTOR.

HAND CRANK SYSTEM REQUIREMENTS: THE FABRIC SHOULD ALWAYS ROLL FROM THE TOP OF ROLLER OR THE FABRIC CAN TEAR. THIS WILL HAPPEN ONLY IF YOU ROLL OUT YOUR AWNING BEYOND THE MAXIMUM EXTENSION OF YOUR AWNING ARMS AS THE FABRIC DROOPS AND CONTINUES TO ROLL BEYOND FABRIC WRAP. AWNING ARMS SHOULD ALWAYS HAVE A BEND AND THE FABRIC SHOULD BE TAUGHT WHEN THE AWNING IS FULLY EXTENDED. THIS IS YOUR MAXIMUM SETTING. IF YOU HAVE ANY QUESTIONS PLEASE CONTACT SUPERIOR ROLL SHADE AWNINGS.